Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/50005DE0080/2
Work Order Type: Weatherization
Audit Name: REVISED

CLIENT INFORMATION

Client Name: 50005DE0080 Address:

Client ID: 50005DE0080 Mason, TN 38049

Alt. Client ID:

CLIENT CONTACT INFORMATION

50005DE0080 (901) 294-2790 Applicant/Person of Record

<u>AGENCY INFORMATION</u>

Agency: Delta Human Resources Agency

Agency Phone: (901) 476-5226

Address: (PO Box 634) 915 Hwy 51 South **Fax:** (901) 476-5258

Covington, TN 38019 *Email Address:*

Agency Contact: Twisdale, Ronnie Work Phone: (901) 476-5226

Cell Phone: (901) 355-4547

Email Address: ronnietwisdale@yahoo.com

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Alt. Client ID:

Measures

		PLACE CARPORT DOOR RT DOOR 36X80			Componen	its			Inspected
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	MASTIC	I Ducts N AND SEAL ALL SUPPL C AND SEAL 11 SUPPLY ROUND RETURN DUCT	REGISTI	ERS V					Inspected
		ROUND SUPPLY DUCT			Estimateo	,		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Sup	•	Each	1					
C	Other Detail								
				Measur	e Sub Total:]	Sub Total:	
	Field Notes:								

	Measure 3 Infiltr	ation Redctn			Componen		-	nspected	
C	omment B.D.3419	DUCTS LEAKY							
#	Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
1	Miscellaneous Sup	-	Each	2		Total			Total
2	Miscellaneous Sup	REPLACE CASING AND TIGHTEN HARDWARE FRONT DOOR.	Each	1					
3	Miscellaneous Sup	TIGHTEN HARDWARE ON BACK DOOR. TIGHTEN HARDWARE ON BACK DOOR.	Each	1					
4	Miscellaneous Sup	REPLACE BRICK MOLD 1.5X60" AND CAULK WINDOW 8 REPLACE BRICK MOLD 1.5X60" AND CAULK WINDOW 8	Each	1					
5	Miscellaneous Sup	CAULK AROUND EXAUST FAN COVER BOTH BATHROOMS	Each	2					
6	Miscellaneous Sup	UPGRADE ATTIC ACCESS AND W/S	Each	1					
7	Miscellaneous Sup	FOAM PLUMBING PENETRATION KITCHEN BATHROOMS AND BEHIND WASHER.	Each	4					
8	Miscellaneous Sup	AIR SEAL AT AT CHIMNEY AT FIREPLACE	Each	1					
9	Miscellaneous Sup	FOAM AROUND DRYER VENT INTERIOR	Each	1					
10	Miscellaneous Sup	FOAM AROUND VENT COVER (DRYER) AND WATER FAUCITS EXTERIOR.	Each	4					

C	Other Detail				1				
				Measur	e Sub Total:] ;	Sub Total:	
	Field Notes:								
1	Measure 4 Lig	ghting Retrofits			Componen	nts DININ RM	NG RM,F	FAMILY	Inspected
C	omment PLAC	E 4 BLUBS IN LIVING RM.	AND 2 IN	I DININ	NG RM. Estimated	,		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Lighting	Compact Fl 13 Watt	Each Lamp	2					
2	Labor	Compact Fl 13 Watt	Each Lamp	2					
3	Lighting	Compact Fl 13 Watt	Each Lamp	4					
4	Labor	Compact Fl 13 Watt	Each Lamp	4					
C	Other Detail						-		
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

IV	leasure 5 DWH	Tank Insulation			Componen	ts		ı	Inspected
Co	mment W/H LO	CATED IN ATTIC.							
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipm	DHW Tank Insulation	Each	1					
2	Labor	DHW Tank Insulation	Each	1					
Of	her Detail								
	ioi zotan								
				Measur	e Sub Total:			Sub Total:	
F	Field Notes:								
	leasure 6 DWH	l Pipe Insulation			Componen	ts		1	Inspected
		l Pipe Insulation			Componen Estimated			Actual	Inspected
Co		Pipe Insulation Description / Comment	Units	Qty	•		Qty		Inspected
C o	mment	·	<i>Units</i> Each		Estimated		Qty	Actual	
C o # 1 1	mment Material / Labor	Description / Comment		Qty	Estimated		Qty	Actual	
Co # 1 1	mment Material / Labor Insulation	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated		Qty	Actual	
# 1 1	mment Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated		Qty	Actual	
Co # 1 1	mment Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated		Qty	Actual	
# 1 1	mment Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1 1	Estimated			Actual	
# 1 1 2 Ott	mment Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	
# 1 1 2 Ott	Material / Labor Insulation Labor her Detail	Description / Comment DHW Pipe Insulation	Each	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	

	igerator Rplcmnt			Componen	ts			Inspected
Comment REMOV	E OLD UNIT FROM HO	ME.						
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Refrigerators	any - any	Each	1					
Other Detail						1		
			Measur	e Sub Total:		,	Sub Total:	
Field Notes:								
Measure 8 Repl	ace A/C			Componen	ts AC1			Inspected
Comment SIZE UP	UNIT ACCORDING TO	MANUAL	. J.INC	LUDE NEW	EVAPOR	RATOR	}	
COIL.RE	EMOVE EXISTING WIND	DOM NNI.						
			15.					
			15.	Estimated	<u>'</u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty		Total
# Material / Labor1 Cooling Equipmen	•	<i>Units</i> Each				Qty	Actual	Total
1 Cooling Equipmen	Central A/C -	Each	Qty 1			Qty	Actual	Total
	•		Qty			Qty	Actual	Total
1 Cooling Equipmen	Central A/C -	Each	Qty 1			Qty	Actual	Total
1 Cooling Equipmen2 Labor	Central A/C -	Each	Qty 1			Qty	Actual	Total
1 Cooling Equipmen2 Labor	Central A/C -	Each	Qty 1			Qty	Actual	Total
1 Cooling Equipmen2 Labor	Central A/C -	Each Each	Qty 1 1				Actual	Total
 Cooling Equipmen Labor Other Detail 	Central A/C -	Each Each	Qty 1 1	Unit Cost			Actual Unit Cost	Total
1 Cooling Equipmen2 Labor	Central A/C -	Each Each	Qty 1 1	Unit Cost			Actual Unit Cost	Total
 Cooling Equipmen Labor Other Detail 	Central A/C -	Each Each	Qty 1 1	Unit Cost			Actual Unit Cost	Total

	easure 9 CO N	Monitor is Needed			Componen	ts		ı	Inspected
					Estimated			Actual	
# Ma	aterial / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 H	ealth and Safety	CO monitor	Each	1					
2 La	abor	Labor	Each	1					
Othe	er Detail						1		
					e Sub Total:			Sub Total:	
	eld Notes:			IVICASUI	e Sub Total.				
	Exh a nment BATHRO	mproper Venting of Ba aust Fan DOM EXAUST FAN TER MINATE OUTSIDE.				BE EXTE	ENDED		Inspected
					Estimated			Actual	
	aterial / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 H	ealth and Safety	Equipment	Each	1					
2 La	abor	Labor	Hour	1					
Othe	er Detail								
]		
				Measur	e Sub Total:			Sub Total:	

Report Run On: 9/16/2011

Measure 11 Smoke Detector is Needed				Components					Inspected	
C	omment									
					Estimated	<u> </u>		Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Health and Safety	Smoke detector	Each	1						
2	Labor	Labor	Each	1						
C	Other Detail			1			7			
				Measur	e Sub Total:] ,	Sub Total:		
	Field Notes:									
L										
			Work O	rder Gra	nnd Total:		Gran	d Total:		